

Cordless Scanners

Batteries

The battery for the cordless scanner is a rechargeable Nickel Metal Hydride (NiMH) pack that, when fully charged, provides up to 18,000 scans or 25 hours of continuous use. The unique design of the battery allows the battery pack to be directly charged in a two prong 120 volt wall outlet commonly used in North America.

For other parts of the world with different voltages and frequencies, the universal charge strip is needed. While the battery pack may be charged directly with 240 volts, the universal charge strips provide the method to physically adapt to the various power plug and socket configurations.

IT3870/ST3470/ST5770

NiMH battery


Base: (L xW) 3.4" x 1.8" /

8.64cm x 4.57cm

Height: 3.3" / 8.38cm

Charging Voltage: 120 VAC /
240 VAC, 50 HZ / 60 Hz

CLESS/NIMH/S



Cover

The cover is made of tough and durable ballistic nylon fabric. The cover is designed to be used in applications where a tool balancer is needed.

ST3470/ST5770

34/5770/COVER



Charge Pack Adapters

Charge pack adapters allow the charge pack to be plugged directly into many international outlet receptacles. After the charge pack is removed from the reader, just snap on an adapter and plug into an outlet.

When the adapter is used in 240 volt applications, only use charge pack CLESS/NIMH/S. Do not attempt to charge part numbers: 34/5770/NICAD, 34/5770/NIMH, 34/5770/NIMH/F, or 34/5770/NICAD/F.



IT3870/ST3470/ST5770

Europlug CEE 7/16


United Kingdom BS 1363

CLESS/ADAPTEURO


CLESS/ADAPTUK



UK Adapter



Europlug Adapter



Cordless Scanners

Holders

Wall mount kits

Wall mount kit (Standard). For use when the scanner is stored conveniently on a wall for easy access.

The scanner rests between two rubber fingers that hold the scanner handle.

Base: (L x W) 6" x 3" / 15.24cm x 7.62cm

Height: 4.75" / 12.07cm

Material: Plastic and rubber

CLESS/WMK/STD

Wall mount kit (Industrial). Similar to the standard holder, except the throat of the holder is smaller to maintain a firmer grasp on the scanner. This kit includes mounting hardware to attach the holder to a forklift truck.

Base: (L x W) 8" x 3" / 20.32cm x 7.62cm

Height: 4.75" / 12.07cm

Material: Plastic and rubber with a metal mounting bracket

CLESS/WMK/IND

Belt Holster

The belt holster, worn on the user's belt, is used to hold the scanner when it is not in use but still needs to be readily accessible.

Base: (L x W) 6" x 3.3" / 15.24cm x 8.38cm

Material: Foam covered wire frame clasped to an adjustable nylon web belt

CLESS/BH



Base Wall Mount Bracket

For applications where ST2070 Base needs to be firmly mounted to a wall. The bracket slides into the molded feature on the back side of the base.

2070/BACKET



Industrial

Standard

Universal Charge

Two or six outlet charge strips are offered to charge more than one battery pack. The strip uses a standard PC (IEC 320) grounded power cord. International versions of the power cords are provided by Hand Held Products' country partners or local PC suppliers.

When the charge strip is used in 240 volt applications, only use battery 34/5770/NIMH/S. Do not attempt to charge battery part numbers: 34/5770/NICAD, 34/5770/NIMH, 34/5770/NIMH/F, or 34/5770/NICAD/F.

IT3870/ST3470/ST5770

2-bay (includes IEC/120V power cord) **CLESS/UC2/SC**

2-bay (without power cord) **CLESS/UC2/S**

6-bay (includes IEC/120V power cord) **CLESS/UC6/SC**

6-bay (without power cord) **CLESS/UC6/S**

